

TMS

Quick workholding change system

TMS is a manual quick workholding change system with a self centering on its taper/face and a pull back system by 3 quick-locking screws in a half turn of the key.

APPLICATION

- Any machining processes

TECHNICAL FEATURES

- Actuation: By a simple cylinder
- Attachment: 6, 8, 11 et 15''
- Workholding interchangeability is performed by an Operator

ADVANTAGES

- High Accuracy: Concentricity $\leq 5\mu$
- Simple and fast, saving your time during change over, allowing flexibility to your machines.

